



## Mold Investigation Rates

As of 4/1/2023

Item	Price
Investigation w/Summary Report w/Scope of Work (if remediation needed)	\$600.00
Investigation w/Summary Report (remediation not needed)	\$500.00
Investigation w/Emailed Findings <u>and</u> Scope of Work	\$500.00
Investigation w/Emailed Findings <u>or</u> Scope of Work	\$450.00
Investigation Only (No GHSC Report – Verbal Discussion Only)	\$400.00
Post-Remediation Inspection (\$50 off job initially investigated by GHSC)	\$500.00
Recheck Inspection (for Post-Remediation Failures)	\$400.00
Infrared Thermal Imaging (charged hourly, to nearest .25-hour, \$50 minimum)	\$225.00
Substructure Inspection Fee	\$150.00
Sample Fee, Standard (2.5 business day turnaround)	\$100.00
Sample Fee, 1.5 business day turnaround	\$125.00
Sample Fee, 5:00 pm next business day turnaround	\$150.00
Sample Fee, 2:00 pm next business day turnaround	\$175.00
Lab Hand-Deliver Fee (cuts overnight shipping off turnaround time)	\$150.00

- Investigation fee includes all physical survey of the site, including moisture meter, intrusive inspection (borescope, cutting inspection hatches, or loosening baseboards) as needed and labor to collect samples.
- Inspection fee is for up to 1.5 hours on-site labor. Additional time beyond 1.5 hours on-site labor is charged at \$225/hour to the nearest quarter hour.
- Overtime hours (nights, weekends) inspections have a 50% surcharge on the investigation fee.
- Holiday inspections have a 100% surcharge (i.e., double) on the investigation fee.
- Additional fees may be applied for drive times over 30 minutes.

Gold Health and Safety Consulting, Inc.  
4001 Inglewood Ave., Suite 101-292, Redondo Beach, CA 90278  
(310) 219-1955 – 0 · (310) 219-1934 – F  
[WWW.Goldsafety.net](http://WWW.Goldsafety.net) · [Dave@GoldSafety.net](mailto:Dave@GoldSafety.net)